


FIG. 2








FIG. 3





4/12

FIG. 4




FIG. 5





FIG. 6







FIG. 8







FIG. 10






FIG. 12





FIG. 13



## 1 1/1 2

FIG. 14





FIG. 15



## 12/12

5 2 ······SPINDLE MOTOR
5 3 ······HEAD
5 4 ······CONTROLLER
5 5 ······LASER DRIVE CIRCUIT
5 6 ······LENS DRIVE CIRCUIT
5 7 ······FOCUS SERVO TRACKING CIRCUIT
5 8 ······TRACKING SERVO CIRCUIT
5 9 ······LASER CONTROL CIRCUIT
S 1 ······RECORDING FIRST TEST SIGNALS
S 2 ······DETERMINING AN OPTIMUM LEVEL PB0 OF PB
S 3 ······RECORDING SECOND TEST SIGNALS
S 4 ······DETERMINING AN OPTIMUM LEVEL PW0 OF PW
S 5 ······STORING PB0 AND PW0
S 1 1 ······RECORDING SECOND TEST SIGNALS
S 1 2 ······TENTATIVELY DETERMINING AN OPTIMUM LEVEL PWO OF PW
S 1 3 ······ RECORDING FIRST TEST SIGNALS
S 1 4 ······DETERMINING AN OPTIMUM LEVEL PB0 OF PB
S 1 5 ······RECORDING SECOND TEST SIGNALS
S 1 6 ······DETERMINING AN OPTIMUM LEVEL PWO OF PW
S 1 7 ······STORING PB0 AND PW0